






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Zapčásti / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservní deloví / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerwju daju

XX = AA,AD


- 1 A 963 227 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 A 963 817 XX
- 5 A 860 700 NU
- 6 A 963 335 NU
- 7 A 960 500 NU
- 10 A 963 707 NU
- 12 A 960 932 XX B9495
- A 963 708 XX B9612
- 13 A 963 706 XX
- 14 B 960 230 NU
- 16 A 960 470 NU
- 18 A 963 788 NU
- 21 A 962 143 NU
- 25 A 960 263 NU



CERAMIX BLUE
 B 9495 .. B 9612 ..















0511 / A 866 400
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





0,3 MPa 3 bar	50°C	16°C	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
			49,5	49,5	48	46	42,5	41	37	33,5	31	28
65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5	
81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36	

	P	bar		MAX. 10		5			Q (3 bar)
	T	°C		MAX. 80		65			
								I/min	
								B9495	X
								B9612	8

